

John Mascaro's Photo Quiz

John Mascaro is President of Turf-Tec International

Can you identify this sports turf problem?

Problem: Brown lines on field Turfgrass Area: Football fields Location: Central US Grass Variety: Perennial ryegrass

Answer to John Mascaro's Photo Quiz on Page 35

You're Always Ahead of the Game with a COVERMASTER® Raincover...

"Excellent Quality... Competive Prices..."

wrote Johnson Bowie, Associate AD, Drexel University, Philadelphia, PA

Johnson's comments confirm what we hear from the many groundskeepers who use a COVERMASTER® raincover to keep their fields dry and ready for play. Call us and we'll gladly tell you more.

The COVERMASTER® Advantage...

- Superior in strength and UV resistance
- Outstanding heat reflective properties
- Light weight easy to handle
- Widest materials for least number of seams
- Largest choice of weights and colors
- Backed by truly dependable warranties

TARP MACHINE VIDEO! Call, fax or e-mail for a free video,

material samples and a brochure.



IASTERS IN THE ART OF SPORTS SURFACE COVERS

Covers for football and soccer TARP MACHINE[™] lets you roll TARPMATE[™] roller comes in fields are also readily available. the cover on and off in minutes. lengths with safety end caps.

CALL TOLL FREE 1-800-387-5808

TARPMATE[™] roller comes in 3

covermaster.com E-MAIL: info@covermaster.com





John Mascaro's Photo Quiz

>> Answer: from page 17

The brown lines on these football fields are the result of mowing. The Sports Turf Manager at this facility several years ago was using a fairly new rotary mower with an offset cutting unit. The day before this photo was taken, the mower blades were removed, sharpened and replaced. When George Toma saw these stripes on the field the following day, he assumed that the mower blades were put on backwards. Upon initial inspection of the mower, everything appeared to be correct. The blades were nice and sharp and attached correctly. The cutting heights of the decks were also found to be correct. They called out a representative for the mower manufacturer and it was determined that when the mower blades were sharpened, they were sharpened at an incorrect angle. When the blades hit the turf, they were not cutting properly but instead, just beating the grass. To also aggravate things, the incident occurred on a hot summer day when the cool season grass was most susceptible to injury. The mower blades were again removed, re-sharpened with the correct angle and replaced. This solved the problem.

Photo submitted by George P. Toma, natural and artificial turf consultant, Westwood, KS.

If you would like to submit a photograph for John Mascaro's Photo Quiz please send it to John Mascaro, 1471 Capital Circle NW, Ste # 13, Tallahassee, FL 32303 call (850) 580-4026 or email to john@turf-tec.com. If your photograph is selected, you will receive full credit. All photos submitted will become property of *SportsTurf* magazine and the Sports Turf Managers Association.

You can't win the game, if you can't play the game.

